

ISCS - Feature #643

SHL15 (IEC104 IEC102)

07/27/2020 09:20 AM - yufeng wu

| | |
|----------------------------|----------------------------------|
| Status: In Progress | Start date: 07/27/2020 |
| Priority: Normal | Due date: |
| Assignee: | % Done: 0% |
| Category: | Estimated time: 0.00 hour |
| Target version: | Spent time: 0.00 hour |

Description

MOXA DA682B Debian8 FEP3linux win2012 FEP3win
email

xie [xiuguangjie6000@126.com](mailto:xieguangjie6000@126.com)

2020-07-23 16:44

zhadaolin@seisys.cn

IEC104 IEC102

:

1 IEC104 IEC102,

2 pscada IEC104

:

1. 104

0x0001-0x4000

0x4001-0xC000

0xC001-0xD000

2. 102

1 2.

Related issues:

Related to ISCS#FEP - Feature #657: IEC102

Resolved

07/28/2020

09/27/2020

Related to ISCS#FEP - Feature #603: se104_c

Resolved

06/23/2020

History

#1 - 08/11/2020 03:28 PM - xiangyang li

- Related to Feature #657: IEC102 added

#2 - 08/11/2020 03:28 PM - xiangyang li

- Status changed from New to In Progress

#3 - 08/25/2020 03:14 PM - xiangyang li

- Related to Feature #603: se104_c added

Files

SHL15 EMS- (1).xlsx

179 KB

07/27/2020

yufeng wu