

ISCS - Bug #1127

SHL15 occQTISCS3.03 ehdbo TB4009 em\_daq ok

12/24/2020 07:51 AM - yufeng wu

<b>Status:</b>	Resolved	<b>Start date:</b>	12/24/2020
<b>Priority:</b>	High	<b>Due date:</b>	
<b>Assignee:</b>	jy Wang	<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour

Description

QTISCS 3.0.3  
 dac+daq 10.43.91.1 4009DI=34 4007AI=7  
 3  
 ehview  
 1scada--  
 GenDigAlm: Get Alm String Fail PID:9956  
 2  
 DAC (srvstatus) PID:9008  
 ehdbo TB4009DI DI  
 a cctvDI-- em\_daq.exe  
 b cctvDI-- em\_daq.exe  
 em\_daq.exe ehdc  
 6-7  
 ok  
 cctvDI /upload/M15/0 /202012231445bak  
 2  
 20201226 ehdbo DI AI

History

#1 - 12/24/2020 10:10 AM - yufeng wu

- Priority changed from Normal to High

15 em\_daq.exe

#2 - 12/24/2020 11:57 AM - Hanqing Liu

- Assignee set to jy Wang

#3 - 12/28/2020 04:40 PM - jy Wang

beta304 ftp /Develop/Release/QT-ISCS/Beta304 tb4009

#4 - 12/30/2020 09:00 AM - yufeng wu

- Status changed from New to Resolved

SHL15 occ 10.43.91.1  
 em\_nsv.exe 2  
 20201226 ehdbo DI AI