

QT - Bug #2254

Debian10.12-QT -ehgdata- ehview

06/28/2022 04:58 PM - lz tang

Status:	Resolved	Start date:	06/28/2022
Priority:	Normal	Due date:	
Assignee:	lz tang	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour

Description

实时数据

刷新表格 表格设置 暂停 历史表格 实时参数 实时数据 实时操作

全部	NULL	TASK	PSCADA	BAS	IIS	FAS	ACS	PSD	AFC
代码	描述	值	状态	代码					
G09_S08_Z041	防火分区负一层总报警	0	0x00000080	G09_S08_Z042					
G09_S08_Z044	防火分区二总报警	0	0x00000080	G09_S08_Z045					
G09_S08_Z047	防火分区五总报警	0	0x00000080	G09_S08_Z048					
G09_S08_Z050	防火分区八总报警	0	0x00000080	G09_S08_Z051					
G09_S08_Z053	横沥站-横番1号风井区间下行总报警	0	0x00000080	G09_S08_Z054					
G09_S08_Z056	横番1号风井-横沥站区间上行总报警	0	0x00000080	G09_S08_Z057					
G09_S08_Z059	横番1号风井-横番2号风井区间下行总报警	0	0x00000080	G09_S08_Z060					
G09_S08_Z062	万横区间风井-横沥站区间下行总报警	0	0x00000080	G09_S08_Z063					
G09_S08_Z065	横番1号风井-2F总报警	0	0x00000080	G09_S08_Z066					
G09_S08_Z068	万横区间风井-2F总报警	0	0x00000080	G09_S08_Z069					
G09_S08_Z071	防火分区31总报警	0	0x00000080	G09_S08_Z072					
G09_S08_Z074	防火分区34总报警	0	0x00000080	G09_S08_Z075					
G09_S08_Z077	防火分区37总报警	0	0x00000080	G09_S08_Z078					
G09_S08_Z080	防火分区40总报警	0	0x00000080	G09_S08_Z081					
G09_S08_Z083	防火分区43总报警	0	0x00000080	G09_S08_Z084					
G09_S08_Z086	防火分区46总报警	0	0x00000080	G09_S08_Z087					
G09_S08_Z089	防火分区49总报警	0	0x00000080	G09_S08_Z090					
HLS_1#GSBWKQ_FJZT	1#跟随变温控制器风机运行状态	0	0x00000080	HLS_1#GSBWKQ_HTPT					
HLS_1#GSBWKQ_HTTAL	1#跟随变温控制器铁心超温报警	0	0x00000080	HLS_1#GSBWKQ_PDM					

用户:车站管理员 | 角色:车站管理员

ehview.jpg

History

#1 - 07/14/2022 04:15 PM - lz tang

- Status changed from New to Resolved

- % Done changed from 0 to 100

Files

.png	123 KB	06/28/2022	lz tang
ehview.jpg	51.8 KB	06/28/2022	lz tang