

QT - Bug #3071

V3.1.1-ehdbo

06/28/2023 01:59 PM - dj Li

Status:Resolved

Priority:Normal

Assignee:

Category:

Target version:

Start date:06/28/2023

Due date:

% Done:0%

Estimated time:0.00 hour

Spent time:0.00 hour

Description

1.3.1.1Java,Web. chrome64.

2.Debian10.

1.ehdbo.

2.DI->->IO.

3.1,.

4.(1)

5.(2)

| 通道号1 | 通道号2 |
|------|------|
| 1    | 2    |
| 11   | 12   |
| 13   | 14   |
| 3    | 4    |
| 5    | 6    |
| 60   | -1   |
| 61   | 62   |
| 63   | 64   |
| 65   | 66   |

基本信息

|     |                   |            |
|-----|-------------------|------------|
| 317 | 组合式空调机组TK_KT_B1工  | 张江实训站机电    |
| 318 | 变频器TK_KT_B1变频启动控制 | 张江实训站机电    |
| 319 | 变频器TK_KT_B1变频准备控制 | 张江实训站机电    |
| 306 | 组合式空调机组TK_KT_A1工  | 张江实训站机电    |
| 309 | 组合式空调机组TK_KT_A1火  | 张江实训站机电    |
| 629 | UCF-11-11排热风机火灾模式 | 张江实训站EMCS+ |
| 701 | 排热风机UOF-11-11变频通讯 | 张江实训站EMCS+ |
| 653 | 回排风机HPF-11-11变频通讯 | 张江实训站EMCS+ |
| 656 | 组合空调箱KT-11-11变频通讯 | 张江实训站EMCS+ |
| 604 | 回排风机HPF-11-12变频通讯 | 张江实训站EMCS+ |

History

#1 - 07/18/2023 02:24 PM - shixun yan

- Status changed from New to Resolved

Files

|      |         |            |       |
|------|---------|------------|-------|
| .png | 16.3 KB | 06/28/2023 | dj Li |
| .png | 50.8 KB | 06/28/2023 | dj Li |