

ISCS#FEP - Task #3191

Feature # 3122 (Resolved): 水泵plc

水泵plc 1.1.0

11/10/2023 05:22 PM - pengfei xu

Status:	Resolved	Start date:	11/08/2023
Priority:	Normal	Due date:	11/10/2023
Assignee:	pengfei xu	% Done:	100%
Category:		Estimated time:	0.00 hour
		Spent time:	0.00 hour
Defect version:			
Description 水泵 fep_gateway 水泵v5/productkey/devicekey/+水泵 sysload水泵 plc_waterpump 水泵			
Related issues: Related to ISCS#FEP - Bug #3184: FEP-HA水泵			
		Resolved	11/06/2023 11/10/2023

History

- #1 - 11/10/2023 05:22 PM - pengfei xu
- Status changed from New to In Progress
- #2 - 11/10/2023 05:24 PM - pengfei xu
- Related to Bug #3184: FEP-HA水泵 added
- #3 - 11/24/2023 03:49 PM - pengfei xu
- Status changed from In Progress to Resolved
- % Done changed from 0 to 100