

ISCS#FEP - Bug #476

00000000000000000000000000000000 2.0.3 000000000000

04/03/2020 01:45 PM - Hanqing Liu

Status:	New	Start date:	04/03/2020
Priority:	Normal	Due date:	
Assignee:	xiangyang li	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Defect version:			

Description
00000000000000000000000000000000 2.0.3 000000000000

ID	Time	Location	Category	Priority	Status	Description	Assignee	Target Version	Actual Version
1	2020-04-03 13:45:10.446	醉白池站	电力	一级...	未恢复	35KV体醉一开关过流保护跳闸 备用	未确认		
2	2020-04-03 13:45:10.009	醉白池站	电力	一级...	未恢复	35KV体醉一开关过流保护跳闸 动作	未确认		
3	2020-04-03 13:45:05.978	醉白池站	电力	一级...	未恢复	35KV体醉一开关过流保护跳闸 未知	未确认		
4	2020-04-03 13:45:01.651	醉白池站	电力	一级...	未恢复	35KV体醉一开关过流保护跳闸 动作	未确认		

History

#1 - 04/03/2020 03:25 PM - xiangyang li

- Assignee set to xiangyang li
- Target version set to 2.2.3 sp2

#2 - 04/08/2020 12:20 PM - xiangyang li

- Target version changed from 2.2.3 sp2 to 3.0

#3 - 07/03/2020 10:31 AM - xiangyang li

- Target version changed from 3.0 to 3.1

#4 - 09/22/2022 11:30 AM - xiangyang li

- Target version deleted (3.1)

Files

File Name	Size	Created	Author
5e27876cb2869ed7026cc931f2585b0.png	92.3 KB	04/03/2020	Hanqing Liu
5e27876cb2869ed7026cc931f2585b0.png	92.3 KB	04/03/2020	Hanqing Liu