



ISCS - Bug #504

bin3.0

04/20/2020 06:18 PM - Hanqing Liu

Status:	Resolved	Start date:	04/20/2020
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour

Description



- [-] 汇金路站
- [-] 赵巷站
- [-] 嘉松中路站
- [-] 徐泾北城站
- [-] 徐盈路站
- [-] 蟠龙路站
- [-] 诸光路站
- [-] 虹桥火车站站
- [-] 沪青平混合变
- [-] 徐泾车辆段
- [-] 朱家角停车场
- [-] 轨交徐泾主变
- [-] 轨交漕盈主变
- [-] 控制中心办公楼
- [-] 控制中心
- [-] DO点表
- [-] ACC点表
- [-] 限值表
- [-] 序控表
- [-] 序控步骤表
- [-] 计算点表
- [-] 操作数列表
- [-] 联动程序表
- [-] 时间表
- [-] 时段表
- [-] 模式表
- [-] 模式系统表
- [-] 联动步骤表
- [-] 追忆组信息表
- [-] 追忆参数表
- [-] 环控参数表

基本信息			
▼	追忆组	追忆对象代码	量测类型
1	test	ELZ_35KV_ZD1DLQ_ZT	电力双位开关状态
▶ 2	test	ELZ_35KV_ZD1_UBC	电压

Related issues:
 Related to ISCS#FEP - Feature #694: 000000 **Resolved** 08/12/2020

History

- #1 - 08/12/2020 04:59 PM - xiangyang li
 - Related to Feature #694: 000000 added
- #2 - 08/12/2020 04:59 PM - xiangyang li
 - Status changed from New to In Progress
- #3 - 09/16/2020 10:42 AM - Hanqing Liu
 - Status changed from In Progress to Resolved

Files

b610018161d48d8a5c259895665cfea.png	21.2 KB	04/20/2020	Hanqing Liu
08ef0d8284ffb0ed58443cc80b9df2.png	19 KB	04/20/2020	Hanqing Liu
7487a7277f567b3c2b8af2e0b6c2086.png	32.5 KB	04/20/2020	Hanqing Liu