

ISCS - Bug #626

SHL15 se104sPscada15 mbSelf\_tcps RTU

07/15/2020 02:47 PM - Hanqing Liu

<b>Status:</b>	Resolved	<b>Start date:</b>	07/15/2020
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	yufeng wu	<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>Description</b>			

History

#1 - 07/15/2020 02:49 PM - Hanqing Liu

se104sPscada15 mbSelf\_tcps RTUNO ini

#2 - 07/15/2020 02:52 PM - Hanqing Liu

- Status changed from New to In Progress
- Assignee set to Hanqing Liu

#3 - 07/16/2020 10:39 AM - Hanqing Liu

- Assignee changed from Hanqing Liu to yufeng wu

#4 - 08/10/2020 09:57 AM - yufeng wu

- Status changed from In Progress to Resolved

mbSelf\_tcps 65535 Di 65535 AI Di AI rtu dcyx dcy RTU cfg

se104\_sPscada.dll DO