

ISCS#FEP - Bug #528

bin2.2.3sp2

04/27/2020 10:56 AM - Hanqing Liu

Status:	Closed	Start date:	04/27/2020
Priority:	Normal	Due date:	
Assignee:	xiangyang li	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:	2.2.3 sp2	Spent time:	0.00 hour
Defect version:			
Description			
176 214开关装置复归 蓝天路站电力RTU -1 -1			
5...	2020-04-27 10:5...	蓝天路站	PSCADA 事项 未恢复 遥控 214开关装置复归 复归 预置 操作员: 中心设备调 主机: 工作站
5...	2020-04-27 10:5...	蓝天路站	PSCADA 事项 未恢复 遥控 214开关装置复归 复归 返校正确 操作员: 中心设备调 主机: 工作站
5...	2020-04-27 10:5...	蓝天路站	PSCADA 事项 未恢复 遥控 214开关装置复归 复归 执行 操作员: 中心设备调 主机: 工作站
5...	2020-04-27 10:5...	蓝天路站	PSCADA 事项 未恢复 遥控 214开关装置复归 复归 拒动 操作员: 中心设备调 主机: 工作站

History

- #1 - 04/27/2020 01:35 PM - xiangyang li
- Project changed from ISCS to ISCS#FEP

- Assignee set to xiangyang li

- Target version set to 2.2.3 sp2

- #2 - 04/27/2020 02:36 PM - xiangyang li
- Status changed from New to In Progress

- #3 - 04/27/2020 03:32 PM - xiangyang li
- Status changed from In Progress to Resolved

- % Done changed from 0 to 100

- #4 - 09/15/2020 10:30 AM - xiangyang li
- Status changed from Resolved to Closed

Files

	20200427105537.png	9.27 KB	04/27/2020	Hanqing Liu
	20200427105546.png	71 KB	04/27/2020	Hanqing Liu