

ISCS#FEP - Feature #549

RTU UINT16

05/09/2020 11:12 AM - xiangyang li

Status:	Resolved	Start date:	05/09/2020
Priority:	Normal	Due date:	
Assignee:	xiangyang li	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:	3.0	Spent time:	0.00 hour
Defect version:			
Description short 32767 UINT16 65535 65535 -1 TB4009_DIGPOINT.F4009_POINTNO1 smallint -> int TB4009_DIGPOINT.F4009_POINTNO2 smallint -> int TB4007_ANAPOINT.F4007_POINTNO smallint -> int TB4014_ACCPOINT.F4014_POINTNO smallint -> int			
Related issues: Related to ISCS - Feature #475: RTU 65535 Resolved 04/03/2020			

History

#1 - 05/09/2020 11:13 AM - xiangyang li

- Related to Feature #475: RTU 65535 added

#2 - 05/09/2020 02:15 PM - xiangyang li

- Status changed from New to In Progress

#3 - 05/09/2020 03:01 PM - xiangyang li

- Description updated

#4 - 07/03/2020 10:28 AM - xiangyang li

- Status changed from In Progress to Resolved

- % Done changed from 0 to 100