

# ISCS#FEP - Bug #875

SHL15-FEP-cctvSIP em\_daq

09/28/2020 10:55 AM - ren hu

<b>Status:</b> Resolved	<b>Start date:</b> 09/24/2020
<b>Priority:</b> Normal	<b>Due date:</b> 09/28/2020
<b>Assignee:</b> ren hu	<b>% Done:</b> 100%
<b>Category:</b>	<b>Estimated time:</b> 40.00 hours
<b>Target version:</b> FEP_V3.0.2	<b>Spent time:</b> 0.00 hour
<b>Defect version:</b>	
<b>Description</b> 12 em_daq	
<b>Related issues:</b>	
Related to ISCS - Bug #858: SHL15-FEP-cctvSIP em_daq	<b>Resolved</b> <b>09/23/2020</b>
Related to ISCS - Bug #833: FEP_V3.0.2_Debian8RTU libcctvC3gb15.so...	<b>Resolved</b> <b>09/16/2020</b>

## History

### #1 - 09/28/2020 10:56 AM - ren hu

- Related to Bug #858: SHL15-FEP-cctvSIP em\_daq added

### #2 - 09/28/2020 10:56 AM - ren hu

- Related to Bug #833: FEP\_V3.0.2\_Debian8RTU libcctvC3gb15.so em\_daq added

### #3 - 09/28/2020 10:58 AM - ren hu

buf#833 fep cctv

### #4 - 09/28/2020 11:01 AM - ren hu

- % Done changed from 0 to 100

### #5 - 09/28/2020 11:02 AM - ren hu

- Status changed from New to In Progress

### #6 - 09/28/2020 11:13 AM - xiangyang li

- Target version changed from 3.0.2 to FEP\_V3.0.2

### #7 - 10/22/2020 03:59 PM - xiangyang li

- Status changed from In Progress to Resolved